metal progress

Subject Index

Vol. 99, January 1971 through June 1971

Aerospace
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56
Improving Structural Efficiency Through Materials Selection, by Donald Webster 3-81
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93
Weight Watching Spurs Advances in Beryllium Fabrication, Staff Report.. 3-96

Aerospace engines
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran. 3-58

Air conditioners
Materials Systems in Action: The Room Air Conditioner, Staff Report..... 2-80

Aircraft
Improving Structural Efficiency Through Materials Selection, by Donald Webster 3-81
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran. 3-58
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93

Aircraft components
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56

Alloy steels
Cooling Transformation Diagram for AISI 9260 (Data Sheet) 1-90
Survey of Service Center Technology . . . A Major Supplier of Alloy Steels, Staff Report 2-78

Aluminum
Survey of Service Center Technology . . . Diverse Services From Aluminum Supplier, Staff Report 2-74

Aluminum alloys
Where Powder Metallurgy Is Growing . . . Application Outlook for Aluminum P/M Parts, Staff Report 4-60

Ball forming
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56

Beryllium
Weight Watching Spurs Advances in Beryllium Fabrication, Staff Report. 3-96

Boriding
Boriding Steels for Wear Resistance, by Howard C. Fielder and Richard J. Sieraski 2-101

Brazing
Brazing Thin-Gage Titanium Sandwich Structures, by Geof Martin 3-89

Bright plating
The Present and Future of Bright Plating, Staff Report 6-56
What Users Say About Plated Parts, Survey Report 6-61

Coatings
Alloying Improves Paintability of Zinc Coatings, by Paul E. Schnedler..... 6-80

Cobalt alloys
Guide to Selection of Superalloys, by Ward F. Simmons (Data Sheet)..... 3-74

Cold extrusion
Cold Extrusion in Europe, by Karl Sieber 1-93
Guide for Determining Extrusion Parameters, by Ronald J. Drake and James W. Throop (Data Sheet)..... 5-78
How to Predict Cold Extrusion Forces, by Ronald J. Drake and James W. Throop 5-72

Columbium
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler..... 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Conversion chart
Conversion Factors for Stress and Pressure, by Christopher R. Calladine and Oleg D. Sherby (Data Sheet) 2-86

Cooling curves
Cooling Transformation Diagram for AISI 9260 (Data Sheet) 1-90

metal progress

Subject Index

Vol. 99, January 1971 through June 1971

Aerospace
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56
Improving Structural Efficiency Through Materials Selection, by Donald Webster 3-81
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93
Weight Watching Spurs Advances in Beryllium Fabrication, Staff Report.. 3-96

Aerospace engines
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran. 3-58

Air conditioners
Materials Systems in Action: The Room Air Conditioner, Staff Report..... 2-80

Aircraft
Improving Structural Efficiency Through Materials Selection, by Donald Webster 3-81
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran. 3-58
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93

Aircraft components
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56

Alloy steels
Cooling Transformation Diagram for AISI 9260 (Data Sheet) 1-90
Survey of Service Center Technology . . . A Major Supplier of Alloy Steels, Staff Report 2-78

Aluminum
Survey of Service Center Technology . . . Diverse Services From Aluminum Supplier, Staff Report 2-74

Aluminum alloys
Where Powder Metallurgy Is Growing . . . Application Outlook for Aluminum P/M Parts, Staff Report 4-60

Ball forming
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56

Beryllium
Weight Watching Spurs Advances in Beryllium Fabrication, Staff Report. 3-96

Boriding
Boriding Steels for Wear Resistance, by Howard C. Fielder and Richard J. Sieraski 2-101

Brazing
Brazing Thin-Gage Titanium Sandwich Structures, by Geof Martin 3-89

Bright plating
The Present and Future of Bright Plating, Staff Report 6-56
What Users Say About Plated Parts, Survey Report 6-61

Coatings
Alloying Improves Paintability of Zinc Coatings, by Paul E. Schnedler..... 6-80

Cobalt alloys
Guide to Selection of Superalloys, by Ward F. Simmons (Data Sheet)..... 3-74

Cold extrusion
Cold Extrusion in Europe, by Karl Sieber 1-93
Guide for Determining Extrusion Parameters, by Ronald J. Drake and James W. Throop (Data Sheet)..... 5-78
How to Predict Cold Extrusion Forces, by Ronald J. Drake and James W. Throop 5-72

Columbium
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler..... 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Conversion chart
Conversion Factors for Stress and Pressure, by Christopher R. Calladine and Oleg D. Sherby (Data Sheet) 2-86

Cooling curves
Cooling Transformation Diagram for AISI 9260 (Data Sheet) 1-90

Copper
Survey of Service Center Technology . . . Copper Producer Has Service Center, Staff Report 2-76

Editorial
Crisis of Cost, by Allen G. Gray..... 1-55
Making Your Own Opportunities, by Allen G. Gray 4-53
Sheet Steel: Not a Commodity, by Allen G. Gray 5-53
A Special Kind of Innovation Gap, by Allen G. Gray 3-55
A Way to Multiply Savings, by Allen G. Gray 2-67
We Can't Afford Tenth Place, by Allen G. Gray 6-55

Electrocuring
Electrocuring Accelerates Production at Ford, Staff Report 6-89

Electropainting
Electropainting Roundup: 'Here to Stay', Staff Report 6-64

Electroplating
The Present and Future of Bright Plating, Staff Report 6-56
What Users Say About Plated Parts, Staff Report 6-61

Electropolishing
Getting Higher Stress Capacity in Long-Life Springs, by George W. Kurasz and James H. Maker 6-75

Extrusion
Cold Extruding in Europe, by Karl Sieber 1-93
Guide for Determining Extrusion Parameters, by Ronald J. Drake and James W. Throop (Data Sheet) 5-78
How to Predict Cold Extrusion Forces, by Ronald J. Drake and James W. Throop 5-72

Fabrication
Technology Forecast '71 1-79

Finishing
Alloying Improves Paintability of Zinc Coatings, by Paul E. Schnedler..... 6-80
Automation Cuts Finishing Costs, Staff Report 6-91
Automation Speeds Valve Stem Plating, Staff Report 6-87
Electrocuring Accelerates Production at Ford, Staff Report 6-89
Electropainting Roundup: 'Here to Stay', Staff Report 6-64
Guidelines for Economical Phosphating, by Marshall R. Bland 6-67
The Present and Future of Bright Plating, Staff Report 6-56
Selective Plating Trims Cost of Finishing Zinc Die Castings, by Roger E. Marce 6-85
Three-Stage Vapor Degreaser Insures Quality in Cladding Strip, Staff Report 6-83
Troubleshooting Checklist for Phosphating Systems (Data Sheet) 6-72
What Users Say About Plated Parts, Survey Report 6-61

Forging
Where Powder Metallurgy Is Growing . . . Application Outlook for Forging P/M Preforms, Staff Report 4-54

Formability
Consider Both the Steel and Process, by Donald R. Neruda 5-54
Designing for Formability, by David A. Chatfield and Stuart P. Keeler..... 5-60
How Steels and Dies Interact in Forming Shapes, by Arthur S. Kasper.... 5-57

Forming
Ball Forming Solves Contouring Problems, by Wynand W. Brandel and Lawrence S. Klass 3-56

Fractures
Polarized Light Brings Out Details of Fracture Zones, by Cyrus S. Noritake, Frank D. Walsh, and Earl C. Roberts. 2-95

Heating elements
Iron-Base Alloy Has Electric Furnace Applications, by Ulf Franzen 5-103

Heat-resistant alloys
Application Outlook for Superalloy P/M Parts, by Allan S. Bufferd and P. U. Gummeson 4-68
Guide to Selection of Superalloys, by Ward F. Simmons (Data Sheet)..... 3-74

High-speed tool steels
Impact Tests Detect Embrittlement in M52 Tools, by Sam R. Kegley 5-110

High-strength steels
Welding Common Constructional High-Strength Steels, by Donald F. Baxter Jr. 5-82

Iron alloys
Guide to Selection of Superalloys, by Ward F. Simmons (Data Sheet)..... 3-74
Iron-Base Alloy Has Electric Furnace Applications, by Ulf Franzen..... 5-103

Isostatic pressing
Where Powder Metallurgy Is Growing . . . Isostatic Pressing: A Three-Dimensional Process, by Edward D. Weisert and Peter Schwarzkopf 4-71

Joining
Metal Joining Trends, Survey Report.. 5-94

Materials selection
Technology Forecast '71 1-57

Materials systems
Materials Systems in Action: The Gas Range, Staff Report 4-86
Materials Systems in Action: The Room Air Conditioner, Staff Report 2-80

Molybdenum
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Nickel alloys
Guide to Selection of Superalloys, by Ward F. Simmons (Data Sheet) 3-72
New Nickel-Base Alloy Solves Weld-Zone Corrosion Problems, by Robert B. Leonard 3-87
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93

Phosphating
Guidelines for Economical Phosphating, by Marshall R. Bland 6-67
Troubleshooting Checklist for Phosphating Systems (Data Sheet) 6-72

Photoforming
Photoforming Thin Metal Parts, by Robert F. Shenk 3-112

Plasma-arc welding
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66

Plating
Automation Speeds Valve Stem Plating, Staff Report 6-87
The Present and Future of Bright Plating, Staff Report 6-56
Selective Plating Trims Cost of Finishing Zinc Die Castings, by Roger E. Marce 6-85
What Users Say About Plated Parts, Survey Report 6-61

Polarized light
Polarized Light Brings Out Details of Fracture Zones, by Cyrus S. Noritake, Frank D. Walsh, and Earl C. Roberts. 2-95

Powder metallurgy parts
Powder Metallurgy . . . Its Present and Future 4-77
Properties and Applications of Powder Metallurgy Parts, by Sherwood W. McGee (Data Sheet) 4-80
Where Powder Metallurgy Is Growing . . . Application Outlook for Aluminum P/M Parts, Staff Report..... 4-60
Application Outlook for Forging P/M Preforms, Staff Report 4-54
Application Outlook for Superalloy P/M Parts, by Allan S. Bufferd and P. U. Gummeson 4-68
Application Outlook for Titanium P/M Parts, by Robert H. Gassner, S. M. Weiman, and W. R. Raymont..... 4-66
Isostatic Pressing: A Three-Dimensional Process, by Edward D. Weisert and Peter Schwarzkopf... 4-71
Spark Sintering: An Unusual Method, by Robert W. Boesel 4-74

Process engineering
Technology Forecast '71 1-71

Ranges
Materials Systems in Action: The Gas Range, Staff Report 4-86

Refractory metals
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Residual stress
New Production Tool Measures Residual Stresses on the Line, by Carl R. Weymueller 5-66

Sandwich construction
Brazing Thin-Gage Titanium Sandwich Structures, by Geof Martin 3-89

Service centers
The Growing Role of Technology in Service Center Operations, by Robert G. Welch 2-68
Survey of Service Center Technology, Staff Report 2-69
Survey of Service Center Technology . . . Copper Producer Has Service Center, Staff Report 2-76
Diverse Services From Aluminum Supplier, Staff Report 2-74
A Major Supplier of Alloy Steels, Staff Report 2-78
One of the Biggest, Staff Report 2-74
Specialist from Overseas, Staff Report 2-78
A West Coast Giant, Staff Report 2-79

Sheet
Consider Both the Steel and Process, by Donald R. Neruda 5-54
Designing for Formability, by David A. Chatfield and Stuart P. Keeler..... 5-60
How Steels and Dies Interact in Forming Shapes, by Arthur S. Kasper..... 5-57

Shotpeening
Getting Higher Stress Capacity in Long-Life Springs, by George W. Kurasz and James H. Maker..... 6-75

Sintering
Where Powder Metallurgy Is Growing . . . Spark Sintering: An Unusual Method, by Robert W. Boesel 4-74

Solidification
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran. 3-58

Springs
Getting Higher Stress Capacity in Long-Life Springs, by George W. Kurasz and James H. Maker 6-75

Stainless steels
Survey of Service Center Techonolgy . . . Specialist From Overseas, Staff Report 2-78

Steels
Alloying Improves Paintability of Zinc Coatings, by Paul E. Schnedler..... 6-80
Boriding Steels for Wear Resistance, by Howard C. Fiedler and Richard J. Sieraski 2-101
Consider Both the Steel and Process, by Donald R. Neruda 5-54
Designing for Formability, by David A. Chatfield and Stuart P. Keeler..... 5-60
The Growing Role of Technology in Service Center Operations, by Robert G. Welch 2-68
How Steels and Dies Interact in Forming Shapes, by Arthur S. Kasper..... 5-57
Survey of Service Center Technology, Staff Report 2-69
Survey of Service Center Technology . . . One of the Biggest, Staff Report. 2-74
Survey of Service Center Technology . . . A West Coast Giant, Staff Report 2-79
Welding Common Constructional High-Strength Steels, by Donald F. Baxter Jr. 5-82

Structural analysis
Improving Structural Efficiency Through Materials Selection, by Donald Webster 3-81

Structural steels
Welding Common Constructional High-Strength Steels, by Donald F. Baxter Jr. 5-82

Surveys
Metal Joining Trends 5-94
Powder Metallurgy . . . Its Present and Future 4-77
What Users Say About Plated Parts... 6-61

Tantalum
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Technology Forecast
Technology Forecast '71 1-56

Titanium alloys
Brazing Thin-Gage Titanium Sandwich Structures, by Geof Martin 3-89
Where Powder Metallurgy Is Growing . . . Application Outlook for Titanium P/M Parts, by Robert H. Gassner, S. M. Weiman, and W. R. Raymont. 4-66

Tool steels
Impact Tests Detect Embrittlement in M52 Tools, by Sam R. Kegley..... 5-110

Tungsten
Fabricating the Refractory Metals
Part I — The Materials and Their Properties, by Donald R. Mash, Dieter W. Bauer, and M. Schussler. 2-89
Part II — Methods Used to Make Parts, by Donald R. Mash, Dieter W. Bauer, and M. Schussler..... 3-60
Part III — How Typical Parts Are Made, by Donald R. Mash, Dieter W. Bauer, and M. Schussler 4-99

Turbine blades
Process Speeds Up Directional Solidification, by John S. Erickson, William A. Owczarski, and Patrick M. Curran 3-58
Rene 80: A Cast Turbine Blade Alloy, by Earl W. Ross 3-93

Vapor degreasing
Three-Stage Vapor Degreaser Insures Quality in Cladding Strip, Staff Report 6-83

Wear
Boriding Steels for Wear Resistance, by Howard C. Fiedler and Richard J. Sieraski 2-101

Welding
Metal Joining Trends, Survey Report.. 5-94
Plasma-Arc Welding of Jet Engine Components, by J. R. Kelley and W. P. Hughes 3-66
Welding Common Constructional High-Strength Steels, by Donald F. Baxter Jr. 5-82

X-ray diffraction
New Production Tool Measures Residual Stresses on the Line, by Carl R. Weymueller 5-66

Zinc coatings
Alloying Improves Paintability of Zinc Coatings, by Paul E. Schnedler..... 6-80

Zinc die castings
Selective Plating Trims Cost of Finishing Zinc Die Castings, by Roger E. Marce 6-85

AUTHOR INDEX

Bauer, Dieter W. . . 2-89; 3-60; 4-99
Baxter, Donald F. Jr. 5-82
Bland, Marshall R. 6-67
Boesel, Robert W. 4-74
Brandel, Wynand W. 3-56
Bufferd, Allan S. 4-68

Calladine, Christopher R. ... 2-86
Chatfield, David A. 5-60
Curran, Patrick M. 3-58

Drake, Ronald J. 5-72; 5-78

Erickson, John S. 3-58

Fiedler, Howard C. 2-101
Franzen, Ulf 5-103

Gassner, Robert H. 4-66
Gray, Allen G.
1-55; 2-67; 3-55; 4-53; 5-53; 6-55
Gummeson, P. U. 4-68

Hughes, W. P. 3-66

Kasper, Arthur S. 5-57
Keeler, Stuart P. 5-60
Kegley, Sam R. 5-110
Kelley, J. R. 3-66
Klass, Lawrence S. 3-56
Kurasz, George W. 6-75

Leonard, Robert B. 3-87

Maker, James H. 6-75
Marce, Roger E. 6-85
Martin, Geof 3-89
Mash, Donald R. ...2-89; 3-60; 4-99
McGee, Sherwood W. 4-80

Neruda, Donald 5-54
Noritake, Cyrus S. 2-95

Owczarski, William A. 3-58

Raymont, W. R. 4-66
Roberts, Earl C. 2-95
Ross, Earl W. 3-93

Schnedler, Paul E. 6-80
Schussler, M. 2-89; 3-60; 4-99
Schwarzkopf, Peter 4-71
Shenk, Robert F. 3-112
Sherby, Oleg D. 2-86
Sieber, Karl 1-93
Sieraski, Richard J. 2-101
Simmons, Ward F. 3-72

Throop, James W. 5-72; 5-78

Walsh, Frank D. 2-95
Webster, Donald 3-81
Weiman, S. M. 4-66
Weisert, Edward D. 4-71
Welch, Robert G. 2-68
Weymueller, Carl R. 5-66

metal progress

SUBJECT INDEX

Vol. 100, July - December 1971

Alloy steels
Hardenability Bands for 1038H, 1045H, and 1541H . . . SAE Recommended Practice (Data Sheet) 1-85
Hardenability Bands for 1522H, 1524H, 1526H, 15B35H, and 15B37H . . . SAE Recommended Practice (Data Sheet) 4-71
New Bearing Steel Combines High Hardenability, Low Cost, by Craig V. Darragh, James J. Donze, and C. Philip Weigel 6-74
New Prealloyed Steel Powders for Forging Preforms, by Robert A. Huseby 6-84
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Aluminum
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71

Appliances
Materials Systems in Action: The Vacuum Cleaner, Staff Report 5-87

Automobiles
New Auotmotive Poppet Valve Materials, by James M. Cherrie and Edward T. Vitcha 3-54
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Batch-type furnaces
Batch Furnace Line Handles Variety of Mining Equipment, by Paul A. Williams and John Russell 1-90

Bearing alloys
New Bearing Steel Combines High Hardenability, Low Cost, by Craig V. Darragh, James J. Donze, and C. Philip Weigel 6-74

Boron steels
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71

Carbon steels
Hardenability Bands for 1038H, 1045H, and 1541H . . . SAE Recommended Practice (Data Sheet) 1-85
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Carburizing
Cadillac Automates Carburizing of Gears and Pinions, Staff Report 1-68

Casting
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Clad metals
Eisenhower Dollar Is Silver-Copper Sandwich, by Joseph P. Quinn 3-91
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71
Technical Economical Factors in Cladding, by S. H. Butt 3-102

Cleaning
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Continuous casting
Continuously Cast Steel Gains User Appeal, by Robert W. Freeman and Witold Wojcik 1-87

Cooling curves
Continuous Cooling Transformation Diagram for a High-Strength Steel, by Lawrence S. Pope and John D. Grozier (Data Sheet) 5-75

Corrosion environments
Processing Influences Selection of Stainless for Corrosive Environments, by A. Moskowitz 3-104

Eddy current testing
Case Depths Measured Nondestructively, Staff Report 2-55

Editorial
The Benefits of Troubled Times, by Allen G. Gray 3-53
How Much Catching Up Is Needed?, by Allen G. Gray 1-55
A Metric Pay-As-We-Go Plan, by Allen G. Gray 5-57
Partners in Pollution Control, by Allen G. Gray 6-51
Prescription for Productivity, by Allen G. Gray 4-59
Testing: Vital Element in Product Cycle, by Allen G. Gray 2-53

Etching
Tint Etching Improves Resolution and Contrast of Microstructures, by James R. Kilpatrick, Arlan O. Benscoter, and Arnold R. Marder 6-79

Exhaust hoods
Exhaust Systems: Hood Close to Source Is Key Consideration, by Larry A. Thaxton 6-56

Fasteners
New High-Strength Fastener Materials Resist Corrosion, by Sumant Patel and Edward Taylor 3-98

Finishing
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Fluorescent penetrants
Testing Aircraft Parts by NDT Methods, by Kingston G. Wolf 2-57

Forming
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Free-machining steels
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Gears
Cadillac Automates Carburizing of Gears and Pinions, Staff Report 1-68
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56

Hardenability
Determining Hardenability From Composition by Chester F. Jatczak 3-60
Multiplying Factors for Predicting Hardenability of Carburizing Steels (Data Sheet) 3-69
New Hardenability Test for High-Speed Steels, by Peter H. Leckie-Ewing... 2-86
Predicting Hardenability of Carburizing Steels, by Anthony F. de Retana and Douglas V. Doane 3-65

Hardenability bands
Hardenability Bands for 1038H, 1045H, and 1541H . . . SAE Recommended Practice (Data Sheet) 1-85
Hardenability Bands for 1522H, 1524H, 1526H, 15B35H, and 15B37H . . . SAE Recommened Practice (Data Sheet). 4-71

Heat treatment
Batch Furnace Line Handles Variety of Mining Equipment, by Paul A. Williams and John Russell 1-90
Cadillac Automates Carburizing of Gears and Pinions, Staff Report 1-68
Computer Calculates Heat Flow in Induction-Heated Bars, by Robert J. Kasper 1-79
How Much Process Control Do You Actually Need?, by Joseph A. Lincoln.. 1-65
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60
Parameters for Gas Quenching in Vacuum Furnaces, by Cyril Dawes and Ray W. Reynoldson 1-72
Practices for Heat Treating Ferrous P/M Parts, Staff Report 1-74
Quenching Shafts in Vertical Oil Tank, Staff Report 1-90
Salt Bath Austenitizes, Quenches, Tempers, by Gordon J. St.-Germain 1-75

High-strength steels
The Challenge We Face From Steels of Japan, by Allen G. Gray 5-59
Continuous Cooling Transformation Diagram for a High-Strength Steel, by Lawrence S. Pope and John D. Grozier (Data Sheet) 5-75
Press Forming Truck Side Rails From High-Strength Steels, Staff Report.. 5-79
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Inclusions
Rating Stainless Steels for Inclusions, by Sidney G. Cox 2-90

Induction hardening
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56

Induction heating
Computer Calculates Heat Flow in Induction-Heated Bars, by Robert J. Kasper 1-79

Joining
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Laser holography
Inspecting Bonded Structures by Laser Holography, by William J. Harris and Francis J. Clauss 2-63

Machining
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60

Magnetic particle testing
Tests Define Range of Magnetic Particle Inspection, by Gilbert L. Marsh 2-62

Magnetoresistivity
Detecting Surface Flaws in Steel Bars at 90 Tons per Manhour 2-56

Materials systems
Materials Systems in Action: The Vacuum Cleaner, Staff Report 5-87

Mechnical tests
How Sears Tests Its Products 2-78
New Hardenability Test for High-Speed Steels, by Peter H. Leckie-Ewing... 2-86

Metallographic exhibit
A New Way to Reveal Magnetic Domains at High Magnification 6-82

Metallography
Detecting Segregation in Titanium Alloys, by Donald J. Baron and William A. Snell 2-92
Rating Stainless Steels for Inclusions, by Sidney G. Cox 2-90
Tint Etching Improves Resolution and Contrast of Microstructures, by James R. Kilpatrick, Arlan O. Benscoter, and Arnold R. Marder 6-79

Neutralizing
Neutralization: In Most Water Treatments, pH Must Be Adjusted, by

Richard Palmer 6-59

Nitriding
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56

Nodular iron castings
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56

Noise pollution
Measurement of Noise Levels (Data Sheet) 6-67

Nondestructive testing
Applications for Specialized Nondestructive Testing Methods, by Donald J. Hagemaier 2-67
Case Depths Measured Nondestructively, Staff Report 2-55
Detecting Surface Flaws in Steel Bars at 90 Tons per Manhour 2-56
Ford Tests Spindles and Shafts on Production Line 2-54
Inspecting Bonded Structures by Laser Holography, by William J. Harris and Francis J. Clauss 2-63
Nondestructive Methods for Rating Materials, by Donald J. Hagemaier (Data Sheet) 2-72
Testing Aircraft Parts by NDT Methods, by Kingston G. Wolf 2-57
Tests Define Range of Magnetic Particle Inspection, by Gilbert L. Marsh. 2-62

Pipelines
Giant Pipemaking in Japan 5-67

Pollution abatement
Air Quality: New Federal Regulations Aimed at Six Pollutants, by Martin H. Adelman 6-54
Exhaust Systems: Hood Close to Source Is Key Consideration, by Larry A. Thaxton 6-56
Incineration: Getting More Attention for Solids, Liquids, Gases, by Lester Stern 6-58
Kodak Emphasizes Economics in Controlling Pollution, by Robert L. Merle. 6-61
Measurement of Noise Levels (Data Sheet) 6-67
Neutralization: In Most Water Treatments, pH Must Be Adjusted, by Richard Palmer 6-59
Oil Is Common Waste in Metalworking Plants 6-63
Waste Water: Spent Cutting Fluids Often Chief Ingredient, by R. B. Fredrickson 6-56
Water Quality: Finding Out What's Wanted Often the Biggest Problem, by Van Hungerfold 6-52

Powder metallurgy parts
New Prealloyed Steel Powders for Forging Preforms, by Robert A. Huseby.. 6-84
Practices for Heat Treating Ferrous P/M Parts, Staff Report 1-74

Press forming
Press Forming Truck Side Rails from High-Strength Steels, Staff Report.. 5-79

Process control
How Much Process Control Do You Actually Need?, by Joseph A. Lincoln 1-65

Productivity
50 Case Histories: Increasing Productivity in Your Plant 4-112
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Quenching
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56
Parameters for Gas Quenching in Vacuum Furnaces, by Cyril Dawes and Ray W. Reynoldson 1-72
Quenching Shafts in Vertical Oil Tank, Staff Report 1-90

Segregations
Detecting Segregation in Titanium Alloys, by Donald J. Baron and William A. Snell 2-92

Sheet
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71

Specifications
Standards Promote Reliability and Economy, by Walter L. Fleischmann. 5-81

Stainless steels
Processing Influences Selection of Stainless for Corrosive Environments, by A. Moskowitz 3-104
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71

Standards
Standards Promote Reliability and Economy, by Walter L. Fleischmann. 5-81

Steels
The Challenge We Face From Steels of Japan, by Allen G. Gray 5-59
Continuous Cooling Transformation Diagram for a High-Strength Steel, by Lawrence S. Pope and John D. Grozier (Data Sheet) 5-75
Continuously Cast Steel Gains User Appeal, by Robert W. Freeman and Witold Wojcik 1-87
Determining Hardenability from Composition, by Chester F. Jatczak 3-60
Hardenability Bands for 1038H, 1045H, and 1541H . . . SAE Recommended Practice (Data Sheet) 1-85
Hardenability Bands for 1522H, 1524H, 1526H, 15B35H, and 15B37H . . . SAE Recommended Practice (Data Sheet) 4-71
Multiplying Factors for Predicting Hardenbility of Carburizing Steels (Data Sheet) 3-69
Predicting Hardenability of Carburizing Steels, by Anthony F. de Retana and Douglas V. Doane 3-65
Press Forming Truck Side Rails from High-Strength Steels, Staff Report.. 5-79
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82
Selecting and Using Economical Alternative Materials, by Carl R. Weymueller 3-71

Testing
Applications for Specialized Nondestructive Testing Methods, by Donald J. Hagemaier 2-67
Case Depths Measured Nondestructively, Staff Report 2-55
Detecting Segregation in Titanium Alloys, by Donald J. Baron and William A. Snell 2-92
Detecting Surface Flaws in Steel Bars at 90 Tons per Manhour 2-56
Ford Tests Spindles and Shafts on Production Line 2-54
How Sears Tests Its Products 2-78
Inspecting Bonded Structures by Laser Holography, by William J. Harris and Francis J. Clauss 2-63
MP Round Table: Potentials for Increasing Productivity with Existing Technology, Staff Report 4-60
New Hardenability Test for High-Speed Steels, by Peter H. Leckie-Ewing.. 2-86
Nondestructive Methods for Rating Materials, by Donald J. Hagemaier (Data Sheet) 2-72
Rating Stainless Steels for Inclusions, by Sidney G. Cox 2-90
Testing Aircraft by NDT Methods, by Kingston G. Wolf 2-57
Tests Define Range of Magnetic Particle Inspection, by Gilbert L. Marsh 2-62

Titanium
Have You Considered Titanium?, by Kenneth B. Lowrie 3-95

Trucks
Productivity Report: A Look at Automotive Technology in Japan, by Allen G. Gray 4-82

Ultrasonic testing
Testing Aircraft Parts by NDT Methods, by Kingston G. Wolf 2-57

Vacuum furnaces
Modern Heat Treating Practices: Quality at the Right Price, Staff Report.. 1-56
Parameters for Gas Quenching in Vacuum Furnaces, by Cyril Dawes and Ray W. Reynoldson 1-72

Valves
New Automotive Poppet Valve Materials, by James M. Cherrie and Edward T. Vitcha 3-54

Wire rod
Techniques for Producing Wire Rod for Cold Heading, by O. Miki 6-70

Waste disposal
Air Quality: New Federal Regulations Aimed at Six Pollutants, by Martin H. Adelman 6-54
Exhaust Systems: Hood Close to Source Is Key Consideration, by Larry A. Thaxton 6-56
Incineration: Getting More Attention for Solids, Liquids, Gases, by Lester Stern 6-58
Kodak Emphasizes Economics in Controlling Pollution, by Robert L. Merle 6-61
Neutralization: In Most Water Treatments, pH Must Be Adjusted, by Richard Palmer 6-59
Oil Is Common Waste in Metalworking Plants 6-63
Waste Water: Spent Cutting Fluids Often Chief Ingredient, by R. B. Fredrickson 6-55
Water Quality: Finding Out What's Wanted Often the Biggest Problem, by Van Hungerford 6-52

AUTHOR INDEX

Adelman, Martin H. 6-54
Baron, Donald J. 2-92
Benscoter, Arlan O. 6-79
Butt, S. H. 3-102
Cherrie, James M. 3-54
Clauss, Francis J. 2-63
Cox, Sidney G. 2-90
Darragh, Craig V. 6-74
Dawes, Cyril 1-72
de Retana, Anthony F. 3-65
Doane, Douglas V. 3-65
Donze, James J. 6-74
Fleischmann, Walter L. 5-81
Fredrickson, R. B. 6-55
Freeman, Robert W. 1-87
Gray, Allen G. 1-55; 2-53 3-53; 4-59; 4-82; 5-57; 5-59; 6-51
Grozier, John D. 5-75
Hagemaier, Donald J. ..2-67; 2-72
Harris, William J. 2-63
Hungerford, Van 6-52
Huseby, Robert A. 6-84
Jatczak, Chester F. 3-60
Kasper, Robert J. 1-79
Kilpatrick, James R. 6-79
Leckie-Ewing, Peter H. 2-86
Lincoln, Joseph A. 1-65
Lowrie, Kenneth B. 3-95
Marder, Arnold R. 6-79
Marsh, Gilbert L. 2-62
Merle, Robert L. 6-61
Miki, O. 6-70
Moskowitz, A. 3-104
Palmer, Richard 6-59
Patel, Sumant 3-98
Pope, Lawrence S. 5-75
Quinn, Joseph P. 3-91
Reynoldson, Ray W. 1-72
St.-Germain, Gordon J. 1-75
Snell, William A. 2-92
Stern, Lester 6-58
Taylor, Edward 3-98
Thaxton, Larry A. 6-56
Vitcha, Edward T. 3-54
Weigel, C. Philip 6-74
Weymueller, Carl R. 3-71
Wojcik, Witold 1-87
Wolf, Kingston G. 2-57